


THANK YOU!

Thank you for purchasing the PAR KDS. With technology specifically designed for your environment, your success is our passion.




FOR PRODUCT INFORMATION AND FULL USER GUIDE VISIT: <https://support.partech.com/>

1 EXAMINE THE SHIPMENT



Please ensure all equipment is present.


Report any missing or damaged equipment to your PAR Salesperson or PAR Channel Partner.




KDS Controller

2 INVENTORY COMPONENTS

Ensure you have the items listed below in your order.



Rubber Pads




Power Supply




Power Cord

BACK



I/O Ports


FRONT



Bracket Lock



Power Button

PLACE THE RUBBER FEET ON THE CONTROLLER (WHEN NOT MOUNTING)




Place the 4 rubber feet included with the controller on the bottom of the controller in the four corners.

CONNECTING POWER THE CONTROLLER AND PAR MONITOR



MAIN I/O BOARD



1	Audio Output
2	2x USB 3.0
3	HDMI
4	LAN
5	2x COM Ports
6	Power Input
7	Power Output